

NOTICE TO MARINERS

Lowestoft Approaches – East Cardinal/Twin Buoy off Station

UTC BST

Mariners and Port Users are advised that the East Cardinal Twin (or Sewer) Buoy, normal position 52° 28.89'N, 001° 46.24'E, is currently off station. The buoy previously drifted away from its charted position but has now been located and recovered.

The South Cardinal Twin Buoy remains on station in position: 52°28.84'N, 001° 46.25'.

Mariners are requested to consider the temporary absence of the East cardinal Twin buoy when passage planning/navigating in Lowestoft Approaches..

A notice will be issued when the East cardinal Twin Buoy has been re-instated in its charted position.

NTM No.23/2024 is hereby cancelled.

Please contact Lowestoft Port Control, VHF Ch14, Tel. 01502 572286 (Option 3) if further information is required.

Divisional Harbour Master East Anglia

15 May 2024

Notice to Mariners Currently in Force:

2006 No.5 **2007** No.13 **2009** No.19 **2011** No.7, No.10 **2012** No.3, **2013** No.17, No.19, **2015** No.24
2016 No.12 **2017** No.5, No.22, No.24, No.32 **2019** No.18 **2020** No.17, No.24, No.26, No.29, No.47,
No.50, **2021** No.40, No.51, No.54, **2022** No.2, No.25, No.26, **2023** No.1, No.50, No.55 **2024** No.1,
No.13, No.18, No.19, No.20, No.22, No.24